



CERTIFICATE OF CONFORMITY

SAI Global hereby grants:

Tyco Australia Group Pty Limited

ABN 93 076 836 416

Level 3, 37 Dalmore Drive, Caribbean Park, Scoresby, VIC 3179, Australia
8902 N. Interstate 27, Lubbock, TX, 79403, United States
Units A3-A5, Stockport Trading Estate, Yew Street, Stockport, Cheshire, SK4 2JW, United Kingdom

WaterMark Certificate of Conformity

Evaluated to:

WMTS 486:2016 - Sprinklers for home applications

“the WaterMark Licensee” the right to use or arrange the use of the WATERMARK as shown below only in respect of the goods described and detailed on the product schedule identified on www.saiglobal.com which are produced by the WaterMark Licensee or on behalf of the WaterMark Licensee* and which comply with the appropriate Standard referred to above as from time to time amended. The Licence is granted subject to the rules governing the use of the WATERMARK and the Terms and Conditions for certification. The WaterMark Licensee covenants to comply with all the Rules and Terms and Conditions.

This Certificate is issued by a JAS-ANZ accredited certification body. The Scheme Owner, Administering Body and Accreditation Body do not in any way warrant, guarantee or represent that the product the subject of this Certificate conforms to the WaterMark Certification Scheme Rules, nor accepts any liability arising out of the use of the product. The Scheme Owner disclaims to the extent permitted by law, all liability (including negligence) for claims of losses, expenses, damages and costs arising as a result of the use of the product(s) referred to in this Certificate.

Certificate No: WMK26392

Issued : 5 July 2022

Expires : 24 November 2024

Originally Certified : 25 November 2019

Current Certification : 5 July 2022

Calin Moldovean
President, Business Assurance
SAI Global Assurance



WaterMark



ABCB

* For details of manufacture, refer to the licensee

The WaterMark is a registered certification trademark of Australian Building Codes Board ABN 74 599 608 295 and is issued under licence by SAI Global Certification Services Pty Limited (ACN 108 716 669) (“SAI Global”) 650 Lorimer Street, Port Melbourne VIC 3207, GPO Box 5420 Sydney NSW 2001.

This certificate may only be reproduced in its entirety and remains the property of SAI Global and must be returned to SAI Global upon its request. Refer to www.saiglobal.com for the list of product models.



SAI GLOBAL

INFORM. INSPIRE. IMPROVE.

SCHEDULE TO CERTIFICATE OF CONFORMITY

SAI Global hereby grants :

Tyco Australia Group Pty Limited

Level 3, 37 Dalmore Drive, Caribbean Park, Scoresby, VIC 3179, Australia

8902 N. Interstate 27, Lubbock, TX, 79403, United States

Units A3-A5, Stockport Trading Estate, Yew Street, Stockport, Cheshire, SK4 2JW, United Kingdom

WaterMark Certificate of Conformity

Evaluated to:

WMTS 486:2016 - Sprinklers for home applications

Model identification of the goods on which the WATERMARK may be used:

| Model Identification | Model name | Brand name | Product description | Date Endorsed |
|--|------------|------------|--|---------------|
| Rapid Response Series LFII, P/N 51-558-1-155 | TY3584 | TYCO | 5.8 K-factor Concealed Pendent Sprinkler Flat Plate, Wet Pipe System Assembly without cover plate 155°F (68°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 51-558-1-200 | TY3584 | TYCO | 5.8 K-factor Concealed Pendent Sprinkler Flat Plate, Wet Pipe System Assembly without cover plate 200°F (93°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-0-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-0-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-2-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-2-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-3-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-3-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-4-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-4-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-5-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-5-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-6-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-6-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-7-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-7-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-8-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-8-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-9-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-9-135B | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-9-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |

Certificate No: WMK26392

Issued Date: 5 July 2022

This schedule supersedes all previously issued schedules



* For details of manufacture, refer to the licensee

The WaterMark is a registered certification trademark of Australian Building Codes Board ABN 74 599 608 295 and is issued under licence by SAI Global Certification Services Pty Limited (ACN 108 716 669) ("SAI Global") 650 Lorimer Street, Port Melbourne VIC 3207, GPO Box 5420 Sydney NSW 2001. This certificate may only be reproduced in its entirety and remains the property of SAI Global and must be returned to SAI Global upon its request. Refer to www.saiglobal.com for the list of product models.

SCHEDULE TO CERTIFICATE OF CONFORMITY

| Model Identification | Model name | Brand name | Product description | Date Endorsed |
|---|------------|------------|--|---------------|
| Rapid Response Series LFII, P/N 56-891-9-165B | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-X-135 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 139°F (59°C) | 1 Jul 2022 |
| Rapid Response Series LFII, P/N 56-891-X-165 | TY3584 | TYCO | 5.8 K Factor Concealed Pendent Sprinkler Cover Plate Assembly 165°F (74°C) | 1 Jul 2022 |
| RAPID RESPONSE Series LFII, PN-51-211-1-155 | TY1334 | TYCO | 4.2K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-211-1-175 | TY1334 | TYCO | 4.2K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-211-4-155 | TY1334 | TYCO | 4.2K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-211-4-175 | TY1334 | TYCO | 4.2K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-211-9-155 | TY1334 | TYCO | 4.2K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-211-9-175 | TY1334 | TYCO | 4.2K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-1-155 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-1-175 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-3-155 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-3-175 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-4-155 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-4-175 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-9-155 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, P/N-51-212-9-175 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-215-1-155 | TY2334 | TYCO | 4.4K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-215-1-175 | TY2334 | TYCO | 4.4K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-215-4-155 | TY2334 | TYCO | 4.4K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-215-4-175 | TY2334 | TYCO | 4.4K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-215-9-155 | TY2334 | TYCO | 4.4K Residential Horizontal | 21 Jan 2020 |
| RAPID RESPONSE Series LFII, PN-51-215-9-175 | TY2334 | TYCO | 4.4K Residential Horizontal | 21 Jan 2020 |
| TY-FRB, PN-77-370-1-135 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-1-155 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-1-175 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-1-200 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-1-286 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-3-135 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-3-155 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-3-175 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-3-200 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-3-286 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-4-135 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-4-155 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-4-175 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-4-200 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-4-286 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-5-135 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-5-155 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |

Certificate No: WMK26392

Issued Date: 5 July 2022

This schedule supersedes all previously issued schedules



Registered by:

The WaterMark is a registered certification trademark of Australian Building Codes Board ABN 74 599 608 295 and is issued under licence by SAI Global Certification Services Pty Limited (ACN 108 716 669) ("SAI Global") 650 Lorimer Street, Port Melbourne VIC 3207, GPO Box 5420 Sydney NSW 2001. This certificate may only be reproduced in its entirety and remains the property of SAI Global and must be returned to SAI Global upon its request. Refer to www.saiglobal.com for the list of product models.

SCHEDULE TO CERTIFICATE OF CONFORMITY

| Model Identification | Model name | Brand name | Product description | Date Endorsed |
|--|------------|------------|--|---------------|
| TY-FRB, PN-77-370-5-175 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-5-200 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-5-286 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-9-135 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-9-155 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-9-175 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-9-200 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-370-9-286 | TY313 | TYCO | Series TY-FRB, 5.6 K-factor, Upright Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-1-135 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-1-155 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-1-175 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-1-200 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-1-286 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-3-135 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-3-155 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-3-175 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-3-200 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-3-286 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-4-135 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-4-155 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-4-175 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-4-200 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-4-286 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-5-135 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-5-155 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-5-175 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-5-200 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-5-286 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-9-135 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-9-155 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-9-175 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-9-200 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| TY-FRB, PN-77-371-9-286 | TY323 | TYCO | Series TY-FRB, 5.6 K-factor, Pendent Sprinkler | 23 Mar 2020 |
| RAPID RESPONSE Series LFII, P/N 51-112-1-160 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 51-112-1-212 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-0-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-0-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-1-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-1-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-2-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-2-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-3-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-3-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-4-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |

Certificate No: WMK26392

Issued Date: 5 July 2022

This schedule supersedes all previously issued schedules



Registered by:

The WaterMark is a registered certification trademark of Australian Building Codes Board ABN 74 599 608 295 and is issued under licence by SAI Global Certification Services Pty Limited (ACN 108 716 669) ("SAI Global") 650 Lorimer Street, Port Melbourne VIC 3207, GPO Box 5420 Sydney NSW 2001. This certificate may only be reproduced in its entirety and remains the property of SAI Global and must be returned to SAI Global upon its request. Refer to www.saiglobal.com for the list of product models.

SCHEDULE TO CERTIFICATE OF CONFORMITY

| Model Identification | Model name | Brand name | Product description | Date Endorsed |
|---|------------|------------|--|---------------|
| RAPID RESPONSE Series LFII, P/N 56-204-4-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-5-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-5-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-6-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-6-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-7-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-7-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-8-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-8-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-9-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-9-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-X-135 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LFII, P/N 56-204-X-165 | TY3596 | TYCO | 4.9K Factor Concealed Sprinkler Cover Plate Assembly | 17 Apr 2020 |
| RAPID RESPONSE Series LF II, P/N 51-212-5-155 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 10 Feb 2021 |
| RAPID RESPONSE Series LF II, P/N 51-212-5-175 | TY2236 | TYCO | 4.9K Factor Pendent Sprinkler Head | 10 Feb 2021 |
| RAPID RESPONSE Series LFII, 50-520-1-160 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Assembly without cover plate | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-0-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-2-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-3-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-4-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-5-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-6-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-7-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-8-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-9-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 56-204-X-135 | TY2324 | TYCO | 4.2K Factor Concealed Horizontal Sidewall Sprinkler Cover Plate Assembly | 16 Nov 2021 |
| RAPID RESPONSE Series LFII, 51-549-1-155 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Assembly without cover plate | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 51-549-1-200 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Assembly without cover plate | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-0-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-0-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-2-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-2-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-3-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-3-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-4-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-4-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-5-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |

Certificate No: WMK26392

Issued Date: 5 July 2022

This schedule supersedes all previously issued schedules



Registered by:

The WaterMark is a registered certification trademark of Australian Building Codes Board ABN 74 599 608 295 and is issued under licence by SAI Global Certification Services Pty Limited (ACN 108 716 669) ("SAI Global") 650 Lorimer Street, Port Melbourne VIC 3207, GPO Box 5420 Sydney NSW 2001. This certificate may only be reproduced in its entirety and remains the property of SAI Global and must be returned to SAI Global upon its request. Refer to www.saiglobal.com for the list of product models.

SCHEDULE TO CERTIFICATE OF CONFORMITY

| Model Identification | Model name | Brand name | Product description | Date Endorsed |
|--|------------|------------|--|---------------|
| RAPID RESPONSE Series LFII, 56-891-5-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-6-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-6-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-7-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-7-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-8-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-8-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-9-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-9-135B | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-9-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-9-165B | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-X-135 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |
| RAPID RESPONSE Series LFII, 56-891-X-165 | TY2534 | TYCO | 4.9K Factor Concealed Pendent Sprinkler Cover Plate Assembly | 21 Jan 2022 |

End of Record

Certificate No: WMK26392

Issued Date: 5 July 2022

This schedule supersedes all previously issued schedules



Registered by:

The WaterMark is a registered certification trademark of Australian Building Codes Board ABN 74 599 608 295 and is issued under licence by SAI Global Certification Services Pty Limited (ACN 108 716 669) ("SAI Global") 650 Lorimer Street, Port Melbourne VIC 3207, GPO Box 5420 Sydney NSW 2001. This certificate may only be reproduced in its entirety and remains the property of SAI Global and must be returned to SAI Global upon its request. Refer to www.saiglobal.com for the list of product models.